

General Environmental Incident Summary

Incident: 3368 **Date/Time Notice:** 6/26/2014 **DEM Incident No:**
Responsible Party: RockPile Energy Services
Date Incident: 6/26/2014 **Time Incident:** 02:30 am **Duration:** 2 minutes
County: Billings **Twp:** 140 **Rng:** 100 **Sec:** 16 **Qtr:**
Lat: 46.93521 **Long:** -103.29460 **Method:** Address matching
Location Description: Whiting / Pronghorn Fed 44-11PH

Submitted By: Michael Harris **Affiliation:**
Address: 543 8th Street East
City: Dickinson **State:** ND **Zip:** 58601

Received By:

Contact Person: Michael Harris
2225 W. Villard
Dickinson, ND 58601

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: High pressure frac line washed out

Description of Released Contaminant: Water / 0.8 gal F.R. / 0.8gal Econo Max / 0.8 N.E. 601

Volume Spilled: 20.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

High pressure Frac Iron washed out at a connection cause frac fluid to be released onto ground

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Fluid was vacuum up and absorbent pads used to pick up the rest

Wastes Disposal Location: Contacted Mirror Image for clean up and disposal

Agencies Involved:

Updates

Date: 6/26/2014

Status: Reviewed; O&G Lead

Staff: Roberts, Kris

Updated Volume:

Notes:

Release of hydro-fracking water, due to a washout of a fitting connection, remained on location during operations according to the report. NDIC retains oversight. Report forwarded to NDIC, O&G.